

Standard School Name: **Hancock Elementry School.**

Crew Leader: **Gregg Schkade**

Street Address: **1601 Skyline Drive**

Crew Leader Tel: _____

Use additional forms if more than 10 Buildings on campus

City, State Zip: _____

Crew Leader Email: _____

Campus Location Code: _____

Inspection Date: **10.8.2022**

Form: _____ of _____

Summary/Critical Observations:

Overall appearance and condition of site looks good.

Is the campus site accessible without special means of ingress/egress? Y or N

Notes: **No issue accessing site. Parking lots are clear, egress to buildings are clear as well.**

Is there Hurricane Ian related debris on site? Y or N If not, has Hurricane Ian Debris already been removed? Y or N

Notes: **There is a minor amount of brush debris across the property. Cleanup crew is currently on site removing debris.**

Were there any known Hurricane Ian preparation activities? Y or N Please describe the activity and identify who performed work.

Notes: **No preparations were notices. Any preparations could have already been removed.**

Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.

Notes: **There is space to the right of the building for portables if needed.**

Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities

Notes: ***FSS119.071**

Campus Name: _____ Building FISH Number: _____ Damage Key:
 0 - No damage
 Building Name: _____ 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

	Damage (0-3)	Comments & Details
General Site:	1	There was a minor amount of brush on the ground from the storm. Cleanup crews were on site actively removing it. There are several light poles knocked over in the parking lot. Most of which have been moved off to the side for later replacement. Gate at the front entrance had minor damage but everything seem to be operational.
Building Envelope:	1	All buildings had minor damage to exterior flashing, and Possible roof leaks at the ridge vents. Exterior windows could use a power washing from storm debris. One covered walkway connected to building six has a few pieces that were dislodged from the storm. Nothing adjacent to it on the ground. Does not pose any hazard. On building five, there is a walkway light filled with water may need further investigation to locate the source of entry of the water and repair.
Building Interior:	1	Every building on site had a handful of stained ceiling tiles. Majority of the ceiling tiles are located in the center room in between all the classrooms. This is consistent with water entering in through the ridge vents. There are also a handful of other classrooms with stained ceiling tiles. Flooring was dry and all locations of question. Building 11 at the top of the steps of the second floor has a obvious water leak at the bottom, left-hand corner of the window, water stains on the wall as well as on the floor.
Mechanical:	0	All mechanicals appear to be functioning properly
Other:	1	All issues on site are considered minor and do not pose any safety concerns.

Category Reference:
 General Site – trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope – Roof, windows, exterior doors, roof top equipment;
 Building Interior – Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical – Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.