

FEDERAL EMERGENCY MANAGEMENT AGENCY  
**PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE**  
 DATE Oct. 7, 2002

**PART I — APPLICANT INFORMATION**

COUNTY	NAME OF APPLICANT	NAME OF LOCAL CONTACT	PHONE NO.
--------	-------------------	-----------------------	-----------

**PART II — SITE INFORMATION**

KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)

a. DEBRIS REMOVAL	d. WATER CONTROL FACILITIES	g. OTHER (Parks, Recreational Facilities, etc.)
b. PROTECTIVE MEASURES	e. PUBLIC BUILDINGS	
c. ROADS AND BRIDGES	f. PUBLIC UTILITIES	

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)
		<u>HEIGHTS ES. 3421 (HES)</u>

DESCRIPTION OF DAMAGE  
ROOF MEMBRANE DAMAGED 2 STORY EAST/WEST WING 85%. NORTH SOUTH WING 5%. ROOF MATERIALS ON GROUND AROUND BLDG. (PHOTO #2-3-10-11-12-13)

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
PANAPET WALL MEMBRANE DAMAGED OVER MEDIA CENTER LOW ROOF. (PHOTO # 2-17)

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
KITCHEN EXHAUST (HOOD) REMOVED FROM CURBS, OVER COLLAPSED. LOW ROOF. KEF-1 PHOTO #2-6-5

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
EXHAUST FAN LOUSES MISSING HIGH ROOF (2) TWO LOCATIONS. PHOTO #2

SHOOC CLOTH @ PLAYGROUND DAMAGED, SUPPORT STRUCTURE DAMAGED (P 17/18)

IMPACT:	% COMPLETE	COST ESTIMATE

NAME OF INSPECTOR	AGENCY	OFFICE PHONE NO.	HOME PHONE NO.
<u>James Spivey</u>			