

Standard School Name:

Diplomat Middle School

Crew Leader:

Angel Rodriguez

Street Address:

Northwest 16th Terrace

Crew Leader Tel:

973-897-2980

City, State Zip:

Cape Coral, FL

Crew Leader Email:

Rodriguez@VTscans.com

Campus Location Code:

Inspection Date:

10-8-22

Use additional forms if more than 10 Buildings on campus

Form: 1 of 4

Inspected
10-8-22

Summary/Critical Observations:

FSS 119.071*

From Grounds. There is a large amount of **FSS 119.071*** scattered over a wide area. Also a few smaller trees + branches, have to be removed. Roofing needs to be cleaned/removed.

Is the campus site accessible without special means of ingress/egress? Y or N

Notes:

Easy Access

Is there Hurricane Ian related debris on site? Y or N If not, has Hurricane Ian Debris already been removed? Y or N

Notes:

FSS 119.071* Scattered throughout. - Requires Attention.

Were there any known Hurricane Ian preparation activities? Y or N. Please describe the activity and identify who performed work.

Notes:

Not Certain.

Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.

Notes:

There appears to be a large room, parking lot and west side of Damaged Building is a large area of land which can be utilized.

Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities

Notes:


Minimal Damage to these areas. One Light Fixture was observed to of been Damaged By Flying Debris. Minimal Impact

Campus Name: Diplomat Middle School Building FISH Number: _____
 Building Name: Northeast 16th Terrace
Ogee Coral, FL.

Damage Key:
 0 - No damage
 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

	Damage (0-3)	Comments & Details
General Site:	1	Some Trees Damaged
Building Envelope:	2	FSS 119.071* w/ Parapets are TOTALLY Damaged and must Be Replaced - FSS 119.071* Equipment visible. - I Don't Believe any units were Installed on this Roof
Building Interior:	2	Water Intrusion I Some 1st Floor Areas as well as Damaged Carpet, Ceiling Tiles and Sheet Rock walls.
Mechanical:	1	Electric is on in most areas including 2nd floor level
Other:	2	wet ceilings + walls throughout - This is extensive and must be dealt with before anyone can occupy Building.

Category Reference:
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope - Roof, windows, exterior doors, roof top equipment;
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.




Campus Name: Diplomat Middle School Building FISH Number: _____ Damage Key:
 0 - No damage
 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

Building Name: _____

	Damage (0-3)	Comments & Details
General Site:		
Building Exterior Interior		Bldg C - First Floor. Drywall + Electric and windows in these areas class rooms, 06-102, 105 , 107, 106, 110, 112 06-112, 113, 114, 117, Bath room or rest room
Building Interior:		wet walls, carpet, and suspended ceiling tiles. Electric OK in these rooms 06-125 common hallways, 06-118, 119, 06-122, 123 (Electrical room wet ceiling tiles. also one damaged floor fixture.)
Mechanical:		
Other:		

Category Reference:
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope - Roof, windows, exterior doors, roof top equipment;
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.



Campus Name: Diglossa Middle School Building FISH Number: _____ Damage Key:
 0 - No damage
 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

Building Name: _____

	Damage (0-3)	Comments & Details
General Site:		
Interior Building Envelope		- Building 6 - 2nd floor. Mostly wet ceiling tiles, carpet, some cabinets upper and lower. in class Rm 6-225 Electric working
Building Interior:		- Electrical room 6-223 wet ceiling tiles, clean concrete floors Replace 1 2x4 Recessed Floor Fixture. Class Room 6-224 - wet cgt, ceiling tiles partial partial drywall, Electric is working
Mechanical:		Class Room 6-222 same as 6-224 above.
Other:		

Category Reference:
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope - Roof, windows, exterior doors, roof top equipment;
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.