

FEDERAL EMERGENCY MANAGEMENT AGENCY  
PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE

DATE  
Oct. 12, 2002

PART I — APPLICANT INFORMATION

COUNTY	NAME OF APPLICANT	NAME OF LOCAL CONTACT	PHONE NO.
--------	-------------------	-----------------------	-----------

PART II — SITE INFORMATION

KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)

- a. DEBRIS REMOVAL
- b. PROTECTIVE MEASURES
- c. ROADS AND BRIDGES
- d. WATER CONTROL FACILITIES
- e. PUBLIC BUILDINGS
- f. PUBLIC UTILITIES
- g. OTHER (Parks, Recreational Facilities, etc.)

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)
		RIVERDALE HS. 3591 (RHS)

DESCRIPTION OF DAMAGE  
 Building 14-018 VENT STACK MISSING COVER. Pix #36  
 " #38 GUTTER DAMAGED NORTH WEST CORNER Pix #2  
 PORTABLES - STAGED SOUTH-WEST OF BLDG #38 10 LOST AWNINGS - Pix #5-6

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
 PORTABLES - ENTRY STEPS (ALUMINUM) DISPLACED. Pix #6  
 Building #24 SOUTH EAST PARAPET 30 LF. DAMAGED ALUMIN. CAP - Pix #15  
 FLASHING. CHILLED WATER LINE INSULATION DAMAGED 75 LF. Pix #15

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
 Building #25 MISSING SHINGLES (BASEBALL LOCKER/DUGOUT) Pix #22  
 Building #28 " " (CONCESSION STAND) Pix #30  
 STORAGE BUILDING SOUTH OF #28 HAS ROOF DAMAGE APPROX 200 SQ FT. Pix #29

IMPACT:	% COMPLETE	COST ESTIMATE

SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)

DESCRIPTION OF DAMAGE  
 POOL HOUSE MISSING SHINGLES Pix #31  
 Building #6 ROOF-METAL FLASHING - OVER ROOM 6-017 DIS-  
 PLACED. DAMAGED AREA EAST OF CMU (BLOCK) Pix #37

IMPACT:	% COMPLETE	COST ESTIMATE

NAME OF INSPECTOR	AGENCY	OFFICE PHONE NO.	HOME PHONE NO.
JAMES SPURLOCK			