

me: CAPE ELEMENTARY  
4519 VINCOMBS BVD  
CAPE CORAL  
de: 0131

Crew Leader: MIKE RAAB  
Crew Leader Tel: 321 456 7501  
Crew Leader Email: MIKE@GEC-3.COM  
Inspection Date: 6 OCT 22

Use additional forms if more than 10 Buildings on campus  
Form: 1 of 2

Observations: SINGLED ROOFS MUST BE REPLACED. TEMP REPAIRS NEEDED ASAP  
FLAT ROOFS OK  
SOME DEBRIS ON GROUNDS  
6 FALLEN COVERED CANOPIES  
accessible without special means of ingress/egress?  Y or N

any related debris on site?  Y or N If not, has Hurricane Ian Debris already been removed? Y or N

own Hurricane Ian preparation activities? Y or N. Please describe the activity and identify who performed work.  
UNKNOWN

Whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.  
YES, PLENTY OF ROOM

any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities  
POWER IS ON IN MOST OF BUILDING  
WATER IS ON

Campus Name: CAPE DEMONSTRATION

Building FISH Number: 0131

Damage Key:

0 - No damage

1 - Needs minor repairs

2 - Needs major repairs

3 - Destroyed

Building Name: 0131

	Damage (0-3)	Comments & Details
General Site:	1	DOWNED LIMBS ONE TREE ON ROOF SHINGLES EVERYWHERE *FSS119.071 2 MAIN WATERS DOWN
Building Envelope:	1	BUILDINGS W/ SHINGLE ROOFS NEED RE-ROOF FLAT ROOFS OK 6 LOWERED CANOPIES DOWN
Building Interior:	1	W 200 2x2 CORING TILES
Mechanical:	1	ON IN PARTS OF BUILDING W/POWER
Other:		

**Category Reference:**  
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope - Roof, windows, exterior doors, roof top equipment;  
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.