Standard School Name:	Varsity Lakes Middle School	Crew Leader:	Luis Amel Leison			
Street Address:	<i>i</i>	Crew Leader Tel:		Use additional forms if more than 10 Buildings on campus		
City, State Zip:	801 Gunnery Road	Crew Leader Ema	813-564-2096 ili:			
0.07) 00000 2.p.	Lehigh Acres, Florida 33971		lleison@gec-3.com			
Campus Location Code:		Inspection Date:	10/11/2022	Form:of		
Summary/Critical Observat	ions:					
School has power, water, and mechanicals on. Majority of hurricane debris removed from campus. The building has minimal exterior damage (gutters, drip edge, and siding). Interior has minimal ceiling tile damage. No access to roof at the time of the inspection.						
Is the campus site accessible without special means of ingress/egress? Y or N						
Notes:						
Yes!						
Is there Hurricane Ian related debris on site? Y or N If not, has Hurricane Ian Debris already been removed? Y or N						
^{Notes:} Minimal debris remaining.						
	icane lan preparation activities? Y or	N. Please d	escribe the activity and identify who	performed work.		
Notes: No visible preparation activities						
Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.						
Notes: Parking lot and open fields available.						
Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities						
Notes: Damaged signag	ge throughout.					

Campus Name: Varsity Lakes Middle School Building FISH Number: Damage Key: 0 - No damage					
Building Name:			1 - Needs minor repairs 2 - Needs major repairs 3 - Destroyed		
Damage (0 -3)		Comments & De	tails		
General Site:	1	Minimal damaged to signage throughout, portable offices (fencing, awnings, exterior siding). Portable office supports need to be further assessed.			
Building Envelope:	1	Minimal damage to gutters, drip edge, and siding. Assess gym roof damage. No access to roof at the time of the inspection.			
Building Interior:	1	Ceiling tiles throughout. Assess floors at entry points. Minimal damage to portable office carpet, drywall, and ceiling tiles.			
Mechanical:	0	All systems functional at time of inspection.			
Other:	1	Inspect roof.			
Category Reference:					

General Site – trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;

Building Envelope – Roof, windows, exterior doors, roof top equipment;

Building Interior – Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;

Mechanical – Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)

Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.