

FEDERAL EMERGENCY MANAGEMENT AGENCY		PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE	
PART I - APPLICANT INFORMATION		PART II - SITE INFORMATION	
COUNTY LCC		NAME OF APPLICANT	
NAME OF LOCAL CONTACT		NAME OF APPLICANT	
PHONE NO.		PHONE NO.	
DATE		DATE	
<p>KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)</p> <p>a. DEBRIS REMOVAL b. PROTECTIVE MEASURES c. ROADS AND BRIDGES d. WATER CONTROL FACILITIES e. PUBLIC BUILDINGS f. PUBLIC UTILITIES g. OTHER (Parks, Recreational Facilities, etc.)</p>			
SITE NO. GATE- GORY		LOCATION (Use map location, address, etc.) Edgewood Academy 3181 (EA)	
DESCRIPTION OF DAMAGE THE FOLLOWING BUILDINGS HAVE MISSING SHINGLES - 1-2-3, 4-5-6, 7-8-9, 10-11			
IMPACT:		COST ESTIMATE	
IMPACT:		% COMPLETE	
DESCRIPTION OF DAMAGE Building #12 HAS SIDE PANELS DAMAGED, AND ROOF PANELS (PHOTO 12)			
IMPACT:		COST ESTIMATE	
IMPACT:		% COMPLETE	
SITE NO. GATE- GORY		LOCATION (Use map location, address, etc.) EA	
DESCRIPTION OF DAMAGE FORETABLES - NORTH UNIT HAS UNDESPINNING DIS-PANES SOUTH " " WINDOW OUT (BOARDS UP)			
IMPACT:		COST ESTIMATE	
IMPACT:		% COMPLETE	
SITE NO. GATE- GORY		LOCATION (Use map location, address, etc.) EA	
DESCRIPTION OF DAMAGE Building #3 HAS EXHAUST VENT COVER DISPLACED, (LAMPING ON ROOF BEG WIRE ATTACHED. HOLE IN CURB COVERED. (PHOTO #3)			
IMPACT:		COST ESTIMATE	
IMPACT:		% COMPLETE	
NAME OF INSPECTOR James Swindle		AGENCY	
HOME PHONE NO.		OFFICE PHONE NO.	