

Standard School Name:

Street Address:

City, State Zip:

Campus Location Code:

Crew Leader:

Crew Leader Tel:

Crew Leader Email:

Inspection Date:

Use additional forms if more than 10 Buildings on campus

Form: \_\_\_\_\_ of \_\_\_\_\_

Pelican Elementary  
3525 SW 3rd Ave  
Cape Coral, FL 33914

Crew Leader Tel: \_\_\_\_\_  
Crew Leader Email: \_\_\_\_\_  
Inspection Date: 10/8/22

Summary/Critical Observations:

Remove Debris at access Road leading to School  
\*FSS119.071  
Remove section of collapsed Geyser + safe off  
camp + CT Damage structural + insulation

Is the campus site accessible without special means of ingress/egress?  Y or  N

Is there Hurricane Ian related debris on site?  Y or  N If not, has Hurricane Ian Debris already been removed?  Y or  N

Were there any known Hurricane Ian preparation activities?  Y or  N Please describe the activity and identify who performed work.

Notes: Sand Bags observed stacked at back of Main Bldg 1

Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.

Notes: Parking lots or area behind school could be utilized

Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities

Notes: Remove debris at access Road.  
School could open with in week,



# Pelican Elementary

Campus Name: Positive Building FISH Number: \_\_\_\_\_

Building Name: BLD - 1

Damage Key:  
 0 - No damage  
 1 - Needs minor repairs  
 2 - Needs major repairs  
 3 - Destroyed

	Damage (0-3)	Comments & Details :
General Site: Building Envelope		40 LF Collapsed Crpt + 30 + 20 Section started to Buckle Some Debris removed at access to Road leading to school
General Site Building Envelope		↓ Damaged CLF = 30 LF + 20 LF of Lattice 4' High
Building Interior:		01-054 - CT 4 01-013 - WINDOW 1, 15 CT + INS, CRT Glue/Bur 01-066 - CT 3 01-036
Mechanical:		Running
Other:		Power & Water.

**Category Reference:**  
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope - Roof, windows, exterior doors, roof top equipment;  
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.

BLD - on 1st floor



# Pelican Elementary

Campus Name: <u>Pelican (Elementary)</u>	Building FISH Number: _____	Damage Key: 0 - No damage 1 - Needs minor repairs 2 - Needs major repairs 3 - Destroyed
Building Name: <u>BLD 7</u>		

	Damage (0-3)	Comments & Details
General Site:		Minor TMC Debris
Building Envelope:		NVD
Building Interior:		7-202 - CT 1 GRM - 1 FL
Mechanical:		Not Running at time of inspection
Other:		Power & Water & HVAC

**Category Reference:**  
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope - Roof, windows, exterior doors, roof top equipment;  
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.



Pelican

Campus Name: <u>Pelican Elementary</u>		Building FISH Number: _____	Damage Key: 0 - No damage 1 - Needs minor repairs 2 - Needs major repairs 3 - Destroyed
Building Name: <u>BND 6</u>			
	Damage (0-3)	Comments & Details	
General Site:		Minor tree Debris.	
Building Envelope:		NVD	
Building Interior:		6-202 - CT 3 6-210 - CT 1	
Mechanical:		NOT RUNNING at time of INSPECTION	
Other:		Power & Water	
<p><b>Category Reference:</b>                  General Site – trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;                  Building Envelope – Roof, windows, exterior doors, roof top equipment;                  Building Interior – Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;                  Mechanical – Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)                  Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.</p>			



# Pelican Elementary

Campus Name: ~~Pelican~~ Building FISH Number: \_\_\_\_\_ Damage Key:  
 0 - No damage  
 Building Name: Storage Bld 1 - Needs minor repairs  
 2 - Needs major repairs  
 3 - Destroyed

	Damage (0-3)	Comments & Details :
General Site:		Minor Debris removal Tree
Building Envelope		50% Damaged Siding
Building Interior:		No ACCESS
Mechanical:		NA
Other:		NA

**Category Reference:**  
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope - Roof, windows, exterior doors, roof top equipment;  
 Building Interior - Water Intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.