

Standard School Name: Villas Elementary School  
Street Address: 8385 Beacon Blvd.  
City, State Zip: Fort Myers, Florida 33907  
Campus Location Code: \_\_\_\_\_

Crew Leader: Luis Amel Leison  
Crew Leader Tel: 813-564-2096  
Crew Leader Email: lleison@gec-3.com  
Inspection Date: 10/10/2022

Use additional forms if more than 10 Buildings on campus

Form: \_\_\_\_\_ of \_\_\_\_\_

<b>Summary/Critical Observations:</b>  Power, water, and mechanicals on. Minor roof damage, minor debris cleanup.
Is the campus site accessible without special means of ingress/egress? <input checked="" type="checkbox"/> Y or <input type="checkbox"/> N
Notes:  Yes! no major concerns.
Is there Hurricane Ian related debris on site? <input checked="" type="checkbox"/> Y or <input type="checkbox"/> N If not, has Hurricane Ian Debris already been removed? <input type="checkbox"/> Y or <input checked="" type="checkbox"/> N
Notes:  Yes! Most debris has been collected at front of school, but further debris removal around campus is needed.
Were there any known Hurricane Ian preparation activities? <input checked="" type="checkbox"/> Y or <input type="checkbox"/> N. Please describe the activity and identify who performed work.
Notes:  Yes! Few sandbags around main doors.
Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.
Notes:  Parking lots/ open field areas available.
Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities
Notes:  Signage & lighting damage.

Campus Name: <u>Villas Elementary School</u>	Building FISH Number: _____	Damage Key: 0 - No damage
Building Name: _____		1 - Needs minor repairs 2 - Needs major repairs 3 - Destroyed

	Damage (0 -3)	Comments & Details
General Site:	1	Damaged trees & debris removal. Damaged signage. Damaged playground equipment. Damaged awning at courtyard.
Building Envelope:	1	Damaged hood - service/ custodial entrance. Drain clogged at roof. Damaged soffit/ drip edge throughout.
Building Interior:	1	Ceiling tiles throughout.
Mechanical:	1	All systems functional at time of inspection.
Other:	1	Removal of dangerous debris throughout.

**Category Reference:**  
 General Site – trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope – Roof, windows, exterior doors, roof top equipment;  
 Building Interior – Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical – Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.