

FEDERAL EMERGENCY MANAGEMENT AGENCY PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE			DATE <u>10/5/22</u>	
PART I — APPLICANT INFORMATION				
COUNTY	NAME OF APPLICANT	NAME OF LOCAL CONTACT	PHONE NO.	
PART II — SITE INFORMATION				
KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)				
a. DEBRIS REMOVAL	d. WATER CONTROL FACILITIES		g. OTHER (Parks, Recreational Facilities, etc.)	
b. PROTECTIVE MEASURES	e. PUBLIC BUILDINGS			
c. ROADS AND BRIDGES	f. PUBLIC UTILITIES			
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
		<u>Franklin Park Media Center</u>		
DESCRIPTION OF DAMAGE				
<u>Water stain tiles 15-001 above windows to your right once going inside.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
		<u>Franklin Park Media Exterior</u>		
DESCRIPTION OF DAMAGE				
<u>Crack in exterior wall outside back entrance.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
		<u>Franklin Media</u>		
DESCRIPTION OF DAMAGE				
<u>Tile stain middle of Media near Receipt. desk.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
		<u>Franklin Park Main Office</u>		
DESCRIPTION OF DAMAGE				
<u>Tile stain above mail slots 14-013</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
NAME OF INSPECTOR		AGENCY	OFFICE PHONE NO.	HOME PHONE NO.

FEDERAL EMERGENCY MANAGEMENT AGENCY PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE				DATE <u>10-5-22</u>
PART I — APPLICANT INFORMATION				
COUNTY	NAME OF APPLICANT	NAME OF LOCAL CONTACT	PHONE NO.	
PART II — SITE INFORMATION				
KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)				
a. DEBRIS REMOVAL		d. WATER CONTROL FACILITIES		g. OTHER (Parks, Recreational Facilities, etc.)
b. PROTECTIVE MEASURES		e. PUBLIC BUILDINGS		
c. ROADS AND BRIDGES		f. PUBLIC UTILITIES		
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.) <u>Franklin Park</u>		
DESCRIPTION OF DAMAGE <u>16-009A RR stained tile.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.) <u>Franklin Park</u>		
DESCRIPTION OF DAMAGE <u>16-008A RR stained Tile.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.) <u>Franklin</u>		
DESCRIPTION OF DAMAGE <u>16-011 water stain tile above cabinets.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.) <u>Franklin Park</u>		
DESCRIPTION OF DAMAGE <u>Building 16 AC units panels bent</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
NAME OF INSPECTOR		AGENCY	OFFICE PHONE NO.	HOME PHONE NO.

FEDERAL EMERGENCY MANAGEMENT AGENCY PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE				DATE <u>10-5-22</u>
PART I — APPLICANT INFORMATION				
COUNTY	NAME OF APPLICANT	NAME OF LOCAL CONTACT	PHONE NO.	
PART II — SITE INFORMATION				
KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)				
a. DEBRIS REMOVAL		d. WATER CONTROL FACILITIES		g. OTHER (Parks, Recreational Facilities, etc.)
b. PROTECTIVE MEASURES		e. PUBLIC BUILDINGS		
c. ROADS AND BRIDGES		f. PUBLIC UTILITIES		
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
		<u>Franklin Park</u>		
DESCRIPTION OF DAMAGE				
<u>AC unit off 5.001 busted open</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
DESCRIPTION OF DAMAGE				
<u>Building 4 possible water exterior behind paint looks discolored</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
DESCRIPTION OF DAMAGE				
<u>Exterior 10-004 slight wall damage above window</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)		
DESCRIPTION OF DAMAGE				
<u>Playground downed large tree branch not sure if any struck structure.</u>				
IMPACT:			% COMPLETE	COST ESTIMATE
NAME OF INSPECTOR		AGENCY	OFFICE PHONE NO.	HOME PHONE NO.

FEDERAL EMERGENCY MANAGEMENT AGENCY PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE				DATE 10-5-22	
PART I — APPLICANT INFORMATION					
COUNTY		NAME OF APPLICANT		NAME OF LOCAL CONTACT	
				PHONE NO.	
PART II — SITE INFORMATION					
KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)					
a. DEBRIS REMOVAL		d. WATER CONTROL FACILITIES		g. OTHER (Parks, Recreational Facilities, etc.)	
b. PROTECTIVE MEASURES		e. PUBLIC BUILDINGS			
c. ROADS AND BRIDGES		f. PUBLIC UTILITIES			
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
		8-005			
DESCRIPTION OF DAMAGE					
stained tile by window above teachers desk.					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
		16-004A Franklin Park			
DESCRIPTION OF DAMAGE					
Rest room stain tile					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
		Franklin Park			
DESCRIPTION OF DAMAGE					
Out side RR #16-020 in common area stained tile.					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
		16-023 Mechanical Room			
DESCRIPTION OF DAMAGE					
Right outside doors stain tile					
IMPACT:				% COMPLETE	COST ESTIMATE
NAME OF INSPECTOR		AGENCY		OFFICE PHONE NO.	HOME PHONE NO.

FEDERAL EMERGENCY MANAGEMENT AGENCY PRELIMINARY DAMAGE ASSESSMENT SITE ESTIMATE				DATE 10/5/22	
PART I — APPLICANT INFORMATION					
COUNTY		NAME OF APPLICANT		NAME OF LOCAL CONTACT	
				PHONE NO.	
PART II — SITE INFORMATION					
KEY FOR DAMAGE CATEGORY (Use appropriate letters in the "category" blocks below)					
a. DEBRIS REMOVAL		d. WATER CONTROL FACILITIES		g. OTHER (Parks, Recreational Facilities, etc.)	
b. PROTECTIVE MEASURES		e. PUBLIC BUILDINGS			
c. ROADS AND BRIDGES		f. PUBLIC UTILITIES			
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
		The Franklin Park			
DESCRIPTION OF DAMAGE					
Downed tree main parking					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
DESCRIPTION OF DAMAGE					
Downed Tree courtyard behind main office					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
DESCRIPTION OF DAMAGE					
Bent cover alum pole near Rm 7-001					
IMPACT:				% COMPLETE	COST ESTIMATE
SITE NO.	CATE-GORY	LOCATION (Use map location, address, etc.)			
DESCRIPTION OF DAMAGE					
Broken window 5-003					
IMPACT:				% COMPLETE	COST ESTIMATE
NAME OF INSPECTOR		AGENCY		OFFICE PHONE NO.	
				HOME PHONE NO.	