	Hictor Caff.	Crew Leader:	Ed Schlattr	Mett 61	1	
Street Address:	250 Senta Ben	Crew Leader To			Use additional forms if more than 10 Buildings on campus	
City, State Zip:		Crew Leader E	mail:			
Campus Location Code:		Inspection Dat	1018 127		Form:of	
Summary/Critical Observa	tions:		\	1	CC	
F	ull gut + 1	refinsh of i	nterior. Ke	od is tern	0ff	
	•					
Is the campus site accessible without special means of ingress/egress? (Y) or N						
Notes:						
	^					
Is there Hurricane Ian relate	ed debris on site? Y or	N If not, has Hurricane Ian	Debris already been removed	? Y or N		
Notes:						
Wassahan and bassa Har		N N Plane				
Notes:	ricane lan preparation activities?	Y or N. Please	e describe the activity and ide	ntiry wno performed wo	rk.	
-						
Please identify whether the	re is space for temporary facilitie	es and/or modular buildings? Pleas	e note any significant issues v	which might impact their	use.	
Notes: The Color	- propert surre	es and/or modular buildings? Please unding the ball Be on option lighting, fencing/security, and subsu	ding is limit			
Notes: The	- propert surre	unding the ball - Be on option	ding is limit			

Campus Name:		Building FISH Number:	Damage Key: 0 - No damage	
Building Name:			1 - Needs minor repairs 2 - Needs major repairs 3 - Destroyed	
	Damage (0 -3)	Comments	& Details	
General Site:				
Building Envelope:				
Building Interior:		-		
Mechanical:				
Other:				
Building Envelope - Building Interior - N Mechanical – Exter pumps cooling tow	s, light poles, signage – Roof, windows, exte Water intrusion, mole ior transformer, wate ers, etc.)	bleachers, concession buildings, out buildings, scoreboards, canopi rior doors, roof top equipment; I, debris, ceiling systems, flooring systems, interior sheet rock walls or r/fire main valves, interior switch gear, interior electrical distribution	systems; In panels, chiller plants and associated equipment (chillers,	