

Campus Name: Three Oaks Middle School Building FISH Number: \_\_\_\_\_ Damage Key:  
 0 - No damage  
 Building Name: \_\_\_\_\_ 1 - Needs minor repairs  
 2 - Needs major repairs  
 3 - Destroyed

	Damage (0 -3)	Comments & Details
General Site:	0	Exterior grounds was in fair condition. Majority of the debris have already been cleaned up and or moved into piles to be cleared at a later date.
Building Envelope:	1	Majority of the buildings suffered some sort of wind damage to the metal roof and flashing
Building Interior:	1	Majority of the ceiling tile leaks located where in the area of ridge vents and or expansion joints within the metal roofing.
Mechanical:	1	Power/Water are on. Walk in freezer and fridge contain rotten food with mold. Needs to be removed. Freezer not working.
Other:	2	Emergency repairs are required for the walk in fridge and freezer. Freezer is inoperable.

**Category Reference:**  
 General Site – trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;  
 Building Envelope – Roof, windows, exterior doors, roof top equipment;  
 Building Interior – Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;  
 Mechanical – Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)  
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.