

Standard School Name: Bonita Springs MS

Crew Leader: _____

Street Address: 10141 W. Terry St

Crew Leader Tel: _____

Use additional forms if more than 10 Buildings on campus

City, State Zip: Bonita Springs, FL 34135

Crew Leader Email: _____

Inspection Date: 10/9/22

Form: _____ of _____

Campus Location Code: _____

Summary/Critical Observations:
Site Accessible, NVD to exterior, minor ceiling tile damage

Is the campus site accessible without special means of ingress/egress? Y or N

Notes:

Is there Hurricane Ian related debris on site? Y or N If not, has Hurricane Ian Debris already been removed? Y or N

Notes:
Minimal Tree debris remains

Were there any known Hurricane Ian preparation activities? Y or N. Please describe the activity and identify who performed work.

Notes: Not known

Please identify whether there is space for temporary facilities and/or modular buildings? Please note any significant issues which might impact their use.

Notes: NA

Please identify any significant issues with parking, grounds, lighting, fencing/security, and subsurface utilities

Notes: None - school ~~should~~ could open with in the week

Campus Name: Parade Square MS Building FISH Number: _____ Damage Key:
 Building Name: AD-1 0 - No damage
 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

	Damage (0-3)	Comments & Details
General Site:		NVD Minor Debris removed
Building Envelope:		NVD
Building Interior:		01-014C RT-1 Cafeteria 015A - GT-6 027 - CT 014B - RT 24 037A - CT 14A - CT 4
Mechanical:		Running
Other:		Power meter

Category Reference:
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope - Roof, windows, exterior doors, roof top equipment;
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.

stitcher