

Campus Name: FT MEYERS MIDDLE Building FISH Number: 1 Damage Key:
 0 - No damage
 1 - Needs minor repairs
 2 - Needs major repairs
 3 - Destroyed

Building Name: _____

	Damage (0-3)	Comments & Details
General Site:	1	GROUNDS ARE CLEAN MINOR AMOUNT OF DEBRIS
Building Envelope:	1	1 SECTION OF FSS 119.071* BLEW OFF. NEEDS TARP & THEN FINAL REPAIR MISC MINOR LEAKS IN MOST OTHER ROOMS. SHINGLES & FASCIA MISSING FROM PICNIC SHELTER
Building Interior:	1	LIST CEILING TILES
Mechanical:	1	HVAC, ELECTRICAL, & PLUMBING WORKING HOOD VENT SHROUD BLEW OFF
Other:		NA

Category Reference:
 General Site - trees, light poles, signage, bleachers, concession buildings, out buildings, scoreboards, canopies, and playground equipment;
 Building Envelope - Roof, windows, exterior doors, roof top equipment;
 Building Interior - Water intrusion, mold, debris, ceiling systems, flooring systems, interior sheet rock walls systems;
 Mechanical - Exterior transformer, water/fire main valves, interior switch gear, interior electrical distribution panels, chiller plants and associated equipment (chillers, pumps cooling towers, etc.)
 Other - Specific emergency repairs required to render each building safe, sanitary and secure for students and staff to resume school operations.